

2011 KOMATSU PC290 LC-10

Year	Serial Number	Stock Number
2011	KMTPC241P54A25064	1219MC CS CC5064

Hours	Horsepower	Location
7677	213	Southland - Roanoke n/a Roanoke, Texas USA 76262



Category Specifics

Stick Size	137
Stick Condition	Good
Swing Bearing	Good
Boom Condition	Good
Bucket Size	42
Bucket Type	Tooth
Bucket Condition	Good
Counterweight	Good
Pins/Bushings	Good



General Appearance

Guards/Covers/Steps	Fair
Hood/Grill/Fenders	Fair
Glass/Mirrors	Good
Doors	Good
Cab Condition	Fair
Cab Type	Enclosed
Paint	Fair
Seat	Good
Heater	Yes




General Appearance Interior

A/C Condition	Temperature too cold to check.
A/C	Yes



Engine

Engine Manufacturer	Komatsu	
Engine Model	SAA3D107E-2	
Horse Power	213	
Blow-By	Yes	Minor
Oil Leaks?	No	
Smokes	No	
Turbocharger	Yes	
Coolant Leaks	No	
Coolant Levels	Good	




Powertrain

Transmission Type	Hydrostatic
Final Drives	Good
Brakes	Good
Emergency Brake works?	Yes



Chassis	
Pad Type	Steel
Pad Size	31.50



Electrical	
Batteries	Fair
Warning Lights Work	Yes
Gauges Work	Yes
Lights Work	Yes



Hydraulics	
Hoses	Good
Cylinder Rods	Good
Pumps	Good
Hydraulics Leak	Yes Right side unknown source.

